HAZELWOOD MINE FIRE INQUIRY

Submission cover sheet

Post your submission with this cover sheet to:

Submissions Hazelwood Mine Fire Inquiry PO Box 3460 GIPPSLAND MC Vic 3841

Email your submission with this cover sheet to info@hazelwoodinquiry.vic.gov.au.

Title: G	
Title: First Name: ISH	Surname: LEE.
Organisation represented(if applicable):	
Email address:	
Postal address:	TRAFALGAR. 3824
Telephone:	Mobile: 3824
Origin and circumstances of fire	Response to fire by:
Measures by Hazelwood Coal Mine to prevent	Hazelwood Coal Mine
fire	Emergency Services
Application and administration of regulatory	☐ Environmental Agencies
regimes	☐ Public Health Officials
☐ Other (please state)	☐ Other Government Agencies
require more room, please attach a separate page and	tiality not to be appropriate you will be provided with an ait it in a form suitable for publication. as a public document and may be published,

Acknowledgements

I understand that:

- I can be contacted by the Inquiry in relation to my submission.
- Anonymous submission will not be accepted.
- The name or worn or suburb of each submitter will be identified as apart of every published submission. Other contact details will be removed before publishing.
- The Inquiry will not publish submission, if it believes that the submission material is or could be defamatory, offensive, contravenes, anti-discrimination or anti-vilification legislation or is outside the scope of the Inquiry's terms of reference

Signature John R. Lee.	
OR if sending electronically please confirm your acknowledgment by ticking by box	Date 10/4/2014.

1. Introduction

Prior to my retirement in Feb. 1991 I had 37 years service with the State Electricity Commission Vic

24 years of that time (1967-1991) with Fire Services Morwell Open Cut,

12 years (1979-1991) as Fire Service Officer responsible to the Mine manager for fire and flood protection. During that time I experenced the 1977 Morwell open cut fire and was continually involved in the review and research that followed, this review resulted in the establishment of a Fire Service Policy and Code of Practice which complied with the Country Fire Authority Act 1958. In the years that followed to my retirement in 1991 this Code of Practice was strictly adhered to by management of all three open cut mines in the Latrobe Valley and rendered us free of serious fires.

Unfortunately it does appear that the Policy and Code of Practice has gone astray with the present Hazelwood Mine Operators.

2. Concerns

It was with great concern that I followed the event of the recent fire in the Morwell Open Cut (Hazelwood Mine) on TV & Newspaper, I would like to have been able to inspect the mine before making comment but that was not possible. For a grass fire to invade the open cut is possible any time, but for that fire to continue burning and escape back into the grassland approximately one week later and burn to within 400 mts of the Hazelwood power station (as reported) is not acceptable fire fighting - fire prevention standards.

I found the scenes on TV disturbing,

Helicopters dropping water heavily loaded with solids on sloping batters, I felt this was fueling the fire more than extinguishing it,

Monitors designed for fighting fires on highrise bildings spraying fires on rising conveyors, where are the sprinkler systems ? where are the rotary sprays in the open cut ?

Reports of Fire Fighters affected by toxic smoke - Infected cuts from use of contaminated water.

With the proper fire fighting system in place as per the Code of Practice these detrimental affects would be avoided because close proximity extinguishing of the fire would only occur after the main fire was subdued by rotary sprays and sprinkler systems.

3. Conclusion.

In conjunction with my two colleagues Mr Graeme Freashwater and Mr Bill Brown I hope we have the opportunity to enlighten the Board of Inquiry with the knowledge and expertise we gained over many years in the Morwell Open Cut especially in field of Fire Prevention/ Fire Fighting, the expertise may be considered old but it is proven as the record will show, unlike the practice in use in the Hazelwood Mine today which is a failure as the recent fire demonstrated. There are many recomendations we can offer well beyond the scope of this submission.